

## Schedule B – Photographs of Property – 1864 Harvey Avenue

### **2011**

1. North facing view from near entrance on Harvey Avenue – motel units to left, office in centre, with additional motel units in building to rear of Property to right of office building.
2. December 22, 2011 – Office building now boarded-up

### **2014 – March 30**

3. North-east facing view of west side of vacant motel unit building – garbage and discarded material at side and front of building

### **2014 – March 31**

4. North facing view from Harvey Ave. entrance of vacant site and buildings

### **2015 – February 12**

5. North facing view showing rear of boarded-up and vacant motel unit building at southern end of Property– Modu-lok fence not effective barrier to prevent access to rear of building
6. North-west facing view of front porch/entry at rear motel unit building - Items on porch indicative of occupation by transients - Mural in background is on rear of adjacent motel on property to north
7. North facing view from Harvey Ave. entrance
8. Concrete building North area of property door insecure with transient belongings.

### **2015 – July 27**

9. North-east facing view from approximately centre of Property – Collapsed tent and shopping cart consistent with transient occupation

### **2015 – December 31**

10. Interior of motel unit - Personal possessions, bedding and mattress indicating occupation by transients – Boarding up and fencing not effective to prevent entry
11. Same unit, interior view

**2016 – March 14**

12. Plywood pulled back that had previously closed off access to basement/crawl space at the building in the center of the property.
13. East facing view of rear motel building – garbage and debris scattered throughout

**2016 – May 19**

14. Garbage and discarded items on ground between the middle building and the concrete building located at the back of the property.
15. North facing view of rear motel building – debris on porch of boarded-up units
16. Garbage and debris in space between rear of back motel unit on Property and adjacent operating motel on neighbouring property. The operating motel wall is on the left and the wall on the right is the concrete building at the back of the property located at 1864 Harvey Ave.
17. View of boarded-up entrance to eastern unit at rear motel building – clothing and personal items apparently discarded
18. North facing view from Harvey Ave. entrance

**2016 – December 6**

19. East facing view of rear motel unit with make-shift screening of space for sleeping on patio/entrance

**2017 – February 1**

20. East facing view from east boundary of Parkinson Rec Centre of rear of front (south) motel building

**2017 – July 21**

21. Northeast view from Harvey Ave. entrance showing overgrown grass/vegetation
22. North facing view from Harvey Ave. entrance, again showing overgrown grass/vegetation

**2017 - December 7**

23. West facing view of south end of front motel building – Parkinson Rec Centre parking lot in background – tarpaulins mark off area used as sleeping space
24. North facing view of rear motel building – garbage and personal items on patio/entrance – make-shift screening of sleeping space just beyond wall on right edge of photo

## **2018 – February 20**

25. Vacant former office building/manager residence near centre of property – Fire Dept. personnel in attendance responding to fire in building
26. Interior of office building – personal items/debris strewn about interior – Fireplace brick visible at left edge of photo
27. Same
28. Fireplace in office building – location of fire
29. Interior of middle building, location of last structure fire– mattress and bedding indicating transient occupation.

## **2018 – March 7**

30. Exterior basement window of middle building on the property, location of last structure fire.
31. Back concrete building door insecure.
32. View of back property that runs along PRC property and next to middle building towards the back concrete building.

## **2018 – August 7**

33. Vacant motel building that is at the entrance to the property and runs along PRC property.
34. North west corner of the concrete building. (Building blocks now missing becoming a structural issue).
35. Vacant motel building that runs along the PRC property, over-grown weeds.
36. West facing view of middle building on property.

## **2018 – September 8**

37. Front of Old Motel as well middle building in the back ground graffiti and over grown weeds in front of both buildings.
38. Concrete, rear building - front graffiti, over-grown weeds, bbq.
39. Front photo of Old Motel with Modu-lok fence and weeds.
40. Front of property yard area with backhoe.
41. Graffiti on old sign post at front of property facing Harvey Ave.
42. Old Motel boarded up graffiti on building.
43. Weeds over-grown on the boulevard area Harvey Ave.
44. Weeds over-grown and backhoe parked on property.
45. Weeds over-grown at the back between the Old Motel building and middle building on property. Photo taken from PRC parking lot area.

46. Over-grown shrubs at the front of property Harvey Ave impeding sidewalk.
47. Back of Old Motel building area facing PRC parking lot.
48. Weeds over-grown next to middle building on property facing PRC parking lot.
49. Weeds over-grown next to middle building and concrete building as well showing graffiti on concrete building.
50. Concrete building - graffiti, boards set up, unsure why boards are outside.
51. Weeds over-grown next to concrete building.
52. Weeds at the back area of middle building on property, backhoe in the front area. Photo taken from PRC parking lot.
53. Weeds extremely over-grown next to middle building and Old Motel. Photo taken from PRC parking lot.
54. Concrete building - graffiti as well bricks coming apart at the top corner of building, weeds over-grown.